

Work Order ID 78454

January-10-12 9:29:02 AM

78454

Page 1

Item ID: D206-642-311BL

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Skidtube LH

Start Date: 10/01/2012 Start Qty: 1.00

1

Cust Item ID:

Required Date: 25/01/2012 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: M.L.J

Date: 12/01/10 Tooling:

Date:

Run Start *NR1*

QC:

Date: SPC (Y/N):

Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D206-642

Rev N

100

0.00

100

DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D206-642-311 CHG006

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

120

QC4- 100% Inspect kits for completeness

0.00

120

QC

Memo

0.00

Quality Control

ml 12 01 25 ①
for M.L.J 12-1-17

SP 12-01-16.

ml 12 01 25 ①

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 78454

January-10-12 9:29:02 AM

78454

Page 2

Item ID: D206-642-311BL

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Skidtube LH

Start Date: 10/01/2012 Start Qty: 1.00 *1*

Cust Item ID:

Required Date: 25/01/2012 Req'd Qty: 1.00 *1*

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start *NR1*

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130		0.00							
130	Packaging								
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D206-642-311								
	Location: _____								
	PPP Rev: _____								
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.00							
Quality Control									

4/2/12/25
mf
12-01-25

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:07 AM

Page 1

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:J05.10.11Added D3429-1 per CHG004KJ/CP/JLM/EC
IPP Rev:K 07-12-04 ECN 1080p DD verified by:ec
IPP Rev:L 08-09-29 as per DSI9421 DD verified by:EC IPP Rev:M
as per REV.N DD 10.04.19 verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

*D206-642-341

Manufactured No

110

Each

3.0000

D206-642-341

Replacement Skidtube

**



B78449.5P

12-01-25

Location

Loc Qty

Loc Code

FG081

1

57156

0

57160

0

57161

0

69950

1

FG082

2

36550

1

69952

1

D206-648-013

Manufactured No

110

Each

7.0000

D206-648-013

GHW Modification

**



B72402 12/1/12

Location

Loc Qty

Loc Code

FG125

7

71578

2

75825

5

ATTN: D3414-041 - BLUE

B78449

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:07 AM

Page 2

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

*D206-642-311RI *

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

D2932-1

Manufactured No

110 Each

6.0000

**

1

D2932-1

Saddle LH Out, 206

Location

Loc Qty

Loc Code

ST428

6

71060

1

72886

1

73466

4

1X

BLUE

D2933-1

Manufactured No

110 Each

1.0000

**

1

D2933-1

Saddle LH In, 206

Location

Loc Qty

Loc Code

ST421

1

71062

1

1X

BLUE

D2938-1

Manufactured No

110 Each

1.0000

**

1

D2938-1

Saddle LH Out, 206

Location

Loc Qty

Loc Code

ST428A

1

71058

1

1X

BLUE

D2939-1

Manufactured No

110 Each

1.0000

**

1

D2939-1

Saddle LH In, 206

Location

Loc Qty

Loc Code

ST428A

1

71056

1

1X

BLUE

January-10-12 9:29:07 AM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:07 AM

Page 3

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

AN3-41A

Purchased No

110 Each

959.0000

8

8

AN3-41A

Bolt

**

SP

Location

Loc Qty

Loc Code

ST354

959

119042

959

Manufactured No

110 Each

991.0000

16

16

D2652

D2652

Bushing

**

SP

Location

Loc Qty

Loc Code

FG

44

31985

44

ST013

947

73834

15

73836

36

76132

96

76133

400

77135

400

Not

MS21042L3

Purchased No

110 Each

6,089.000

8

8

MS21042L3

Nut

**

SP

Location

Loc Qty

Loc Code

ST300

6089

117441

16

117885

32

118451

5

118927

3

119017

5559

119075

474

SP

AN960JD10

NAS1149D0363J Purchased

No

110 Each

0.0000

8

8

AN960JD10

Washer

**

ml 0142.

January-10-12 9:29:07 AM

Shop Packet Print

Page 3

SP 12-01-10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr.	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:07 AM

Page 4

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

AN5-10A

Purchased

No

110

Each

634.0000

4

4

AN5-10A

Bolt

Location

Loc Qty

Loc Code

ST337

634

118191

80

119547

454

119981

100

Purchased

No

110

Each

1,251.000

4

AN5-11A

AN5-11A

Bolt

Location

Loc Qty

Loc Code

ST337

1251

118191

13

119512

1238

Purchased

No

110

Each

0.0000

AN960JD516

NAS1149D0563J

AN960JD516

Washer

AN4-6A

Purchased

No

110

Each

3,572.000

12

AN4-6A

Bolt

Location

Loc Qty

Loc Code

ST356

3572

119017

3572

Purchased

No

110

Each

0.0000

AN960JD416

NAS1149D0463J

AN960JD416

Washer

January-10-12 9:29:08 AM

Shop Packet Print

Page 4

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:08 AM

Page 5

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

MS21042L4

Purchased

No

110

Each

7,915.000

12

12

MS21042L 4

Nut

**

SP-12-01-16

Location

Loc Qty

Loc Code

ST300

7915

117441

51

117601

342

118451

133

119017

2389

119075

5000

12x

D3407-043

Manufactured

No

110

Each

20.0000

1

1

D3407-043

Tow Ring

**

B78977
SP12-01-28

Location

Loc Qty

Loc Code

ST463

18

68339

2

74519

16

ST464

2

68339

0

71040

1

72513

1

BLUE

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:08 AM

Page 6

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

D3456-1

Manufactured No

110 Each

79.0000

1

D3456-1

Washer

**

Location

Loc Qty

Loc Code

FG

7

25701

7

ST034

50

77486

50

ST044

22

66848

3

71165

2

73493

17

Manufactured No

110 Each

44.0000

2

D3457-1

D3457-1

Washer

**

Location

Loc Qty

Loc Code

FG

10

32409

10

ST044

34

67779

1

71849

3

76231

30

12-01-16

2x

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:08 AM

Page 7

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

MS21043-4

Purchased

No

110

Each

1,058.000

1

MS21043-4

Nut

**

SP

Location

Loc Qty

Loc Code

FG

40

104603

40

ST300

470

118686

470

ST301

548

119309

52

119546

496

12

AN4C5A

Purchased

No

110

Each

399.0000

1

AN4C5A

BOLT

**

SP

Location

Loc Qty

Loc Code

FP002

19

112243

19

ST355

380

112243

280

119017

100

1X

AN960C416

NAS1149C0463
R

Purchased

No

110

Each

0.0000

1

AN960C416

washer

**

M117735 SP
12-01-16

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:08 AM

Page 8

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00

Required Qty: 1.00

D3413-1

Manufactured No

110 Each

59.0000

1

D3413-1

Ring

**

Location

Loc Qty

Loc Code

ST420

2

66387

1

70773

1

ST464

55

73822

3

75478

52

ST473

2

71041

2

BLUE

D2712

Manufactured No

110 Each

1,642.000

10

D2712

Set Screw

**

Location

Loc Qty

Loc Code

FG

50

29962

50

ST021

1592

76065

1592

Manufactured No

110 Each

60.0000

2

D2934

D2934

Saddle Spacer

**

Location

Loc Qty

Loc Code

FG

6

31929

6

ST021

54

74501

19

74883

35

January-10-12 9:29:08 AM

Shop Packet Print

Page 8

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

January-10-12 9:29:08 AM

Page 9

Work Order ID: 78454

78454

Parent Item: D206-642-311BL

***D206-642-311BL ***

Parent Item Name: Skidtube LH

Start Date: 10/01/2012

Required Date: 25/01/2012

Start Qty: 1.00


Required Qty: 1.00

D2935
D2935
Saddle Spacer

Manufactured No

110 Each

56.0000

******  2

Sp 12-01-16

Location

Loc Qty

Loc Code

FG

6

31793

6

ST021

50

74503

20

74882

30

2x

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

4.5 206 L/L-1/L-3/L-4/407 LOW & HIGH GEAR SKIDTUBES

ITEM	QTY -311	QTY -312	QTY -313	QTY -314	QTY -341	QTY -347	QTY -349	QTY -351	QTY -013	PART NUMBER	DESCRIPTION
	X									D206-642-311	SKIDTUBE INSTALLATION, LH
		X								D206-642-312	SKIDTUBE INSTALLATION, RH
			X							D206-642-313	SKIDTUBE INSTALLATION, LH
				X						D206-642-314	SKIDTUBE INSTALLATION, RH
1	1	1			X					D206-642-341	SKIDTUBE
						X				D206-642-347	WEARSHOE KIT (REPLACES -343)
							X			D206-642-349	RUN-ON LANDING WEARPLATE KIT
			1	1				X		D206-642-351	SKIDTUBE
1	1	1	1	1					X	D206-648-013	GROUND HANDLING KIT
1					1					D2650-5	SKIDTUBE ASSEMBLY
1								1		D4361-041	SKIDTUBE ASSEMBLY
2A					14			4		D2651-1	* PLUG ⁽¹⁾
2B					14			4		D2651-3	* O-RING ⁽¹⁾
3					1			1		D2646	* AFT CAP ⁽¹⁾
4					2			2		MS27039-1-08	* SCREW ⁽¹⁾
5					2			2		NAS1149D0332J	* WASHER ⁽¹⁾ (OR AN960JD10L)
6	1		1							D2932-1	SADDLE, FWD OUT, LH
6		1		1						D2932-2	SADDLE, FWD OUT, RH
7	1		1							D2933-1	SADDLE, FWD IN, LH
7		1		1						D2933-2	SADDLE, FWD IN, RH
8	1		1							D2938-1	SADDLE, AFT OUT, LH
8		1		1						D2938-2	SADDLE, AFT OUT, RH
9	1		1							D2939-1	SADDLE, AFT IN, LH
9		1		1						D2939-2	SADDLE, AFT IN, RH
10	8	8	8	8						AN3-41A	BOLT
11	16	16	16	16						D2652	BUSHING
12A	8	8	8	8						MS21042-3	NUT (OR MS21042L3)
12B	8	8	8	8						NAS1149D0363J	WASHER (OR AN960JD10)
13	4	4	4	4						AN5-10A (OR AN5-11A)	* BOLT ⁽²⁾
14	4	4	4	4						AN5-11A (OR AN5-12A)	* BOLT ⁽²⁾
15	8	8	8	8						NAS1149D0563J	WASHER (OR AN960JD516)
16	12	12	12	12						AN4-6A	BOLT
17	24	24	24	24						NAS1149D0463J	WASHER (OR AN960JD416)
18	12	12	12	12						MS21042-4	NUT (OR MS21042L4)
20A					6	6				D3537-1	WEARPAD (REPLACES D2648-3)
21A					1	1				D3537-3	WEARPAD (REPLACES D3429-1)
22A					1	1				D3535-11	WEARSHOE (REPLACES D2656-11)
22B					1	1				D3536-11	GASKET
23A					1	1				D3535-23	WEARSHOE (REPLACES D2656-23)
23B					1	1				D3536-23	GASKET
24A					1	1				D3535-35	WEARSHOE (REPLACES D2656-35)
24B					1	1				D3536-35	GASKET
26A					54	54				MS27039C1-08	SCREW
26B					54	54				NAS1149C0332R	WASHER (OR AN960C10L)
26C					54					ALS7-1032-130	* INSERT ⁽¹⁾ (or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
30	1	1	1	1						D3407-043	TOW RING ASSEMBLY (REPLACES D2968-043)
31	1	1	1	1						D3456-1	WASHER
32	1	1	1	1						D3457-1	WASHER
33	1	1	1	1						MS21043-4	NUT
34	1	1	1	1						AN4C5A	BOLT
35	1	1	1	1						NAS1149C0463R	WASHER (OR AN960C416)
36	1	1	1	1						D3413-1	RING (REPLACES D2655)
37	10	10	10	10						D2712	SET SCREW
38	2	2	2	2						D2934	SADDLE SPACER
39	2	2	2	2						D2935	SADDLE SPACER
40									2	D3414-041	GHW LUG (REPLACES D2659)
41									4	AN3C37A	BOLT
42									8	D2652	BUSHING
43									4	MS21043-3	NUT
44									4	NAS1149C0363R	WASHER (OR AN960C10)

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: 0

Date: 11.06.15

REFERENCE ONLY

DART AEROSPACE USA, INC.

IIN-D206-642

Page 30 of 43

ITEM	QTY -311	QTY -312	QTY -313	QTY -314	QTY -341	QTY -347	QTY -349	QTY -351	QTY -013	PART NUMBER	DESCRIPTION
50							1	1		D4364-041	FWD WEARPLATE ASSY
51							1	1		D4364-043	AFT WEARPLATE ASSY
52							18	18		D3873-1	BUSHING
53							4			D2649	SPACER
54A							9	9		AN3-36A	BOLT
54B							9	9		NAS1149C0332R	WASHER (OR AN960C10L)
54C							9	9		MS21042-3	NUT

NOTES: (1) DENOTES THAT PART IS INCLUDED WITH D2650-5 OR D4361-041 ASSEMBLY ABOVE
(2) CHOICE OF BOLT WILL DEPEND ON CROSSTUBE (SEE INSTALLATION PROCEDURE)

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision: 0

Date: 11.06.15

4.5 206 L/L-1/L-3/L-4/407 LOW & HIGH GEAR SKIDTUBES

ITEM	QTY -311	QTY -312	QTY -313	QTY -314	QTY -341	QTY -347	QTY -349	QTY -351	QTY -013	PART NUMBER	DESCRIPTION
	X									D206-642-311	SKIDTUBE INSTALLATION, LH
		X								D206-642-312	SKIDTUBE INSTALLATION, RH
			X							D206-642-313	SKIDTUBE INSTALLATION, LH
				X						D206-642-314	SKIDTUBE INSTALLATION, RH
	1	1			X					D206-642-341	SKIDTUBE
						X				D206-642-347	WEARSHOE KIT (REPLACES -343)
							X			D206-642-349	RUN-ON LANDING WEARPLATE KIT
			1	1				X		D206-642-351	SKIDTUBE
	1	1	1	1					X	D206-648-013	GROUND HANDLING KIT
1					1					D2650-5	SKIDTUBE ASSEMBLY
1								1		D4361-041	SKIDTUBE ASSEMBLY
2A					14			4		D2651-1	* PLUG ⁽¹⁾
2B					14			4		D2651-3	* O-RING ⁽¹⁾
3					1			1		D2646	* AFT CAP ⁽¹⁾
4					2			2		MS27039-1-08	* SCREW ⁽¹⁾
5					2			2		NAS1149D0332J	* WASHER ⁽¹⁾ (OR AN960JD10L)
6	1		1							D2932-1	SADDLE, FWD OUT, LH
6		1		1						D2932-2	SADDLE, FWD OUT, RH
7	1		1							D2933-1	SADDLE, FWD IN, LH
7		1		1						D2933-2	SADDLE, FWD IN, RH
8	1		1							D2938-1	SADDLE, AFT OUT, LH
8		1		1						D2938-2	SADDLE, AFT OUT, RH
9	1		1							D2939-1	SADDLE, AFT IN, LH
9		1		1						D2939-2	SADDLE, AFT IN, RH
10	8	8	8	8						AN3-41A	BOLT
11	16	16	16	16						D2652	BUSHING
12A	8	8	8	8						MS21042-3	NUT (OR MS21042L3)
12B	8	8	8	8						NAS1149D0363J	WASHER (OR AN960JD10)
13	4	4	4	4						AN5-10A (OR AN5-11A)	* BOLT ⁽²⁾
14	4	4	4	4						AN5-11A (OR AN5-12A)	* BOLT ⁽²⁾
15	8	8	8	8						NAS1149D0563J	WASHER (OR AN960JD516)
16	12	12	12	12						AN4-6A	BOLT
17	24	24	24	24						NAS1149D0463J	WASHER (OR AN960JD416)
18	12	12	12	12						MS21042-4	NUT (OR MS21042L4)
20A					6	6				D3537-1	WEARPAD (REPLACES D2648-3)
21A					1	1				D3537-3	WEARPAD (REPLACES D3429-1)
22A					1	1				D3535-11	WEARSHOE (REPLACES D2656-11)
22B					1	1				D3536-11	GASKET
23A					1	1				D3535-23	WEARSHOE (REPLACES D2656-23)
23B					1	1				D3536-23	GASKET
24A					1	1				D3535-35	WEARSHOE (REPLACES D2656-35)
24B					1	1				D3536-35	GASKET
26A					54	54				MS27039C1-08	SCREW
26B					54	54				NAS1149C0332R	WASHER (OR AN960C10L)
26C					54					ALS7-1032-130	* INSERT ⁽¹⁾ (or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
30	1	1	1	1						D3407-043	TOW RING ASSEMBLY (REPLACES D2968-043)
31	1	1	1	1						D3456-1	WASHER
32	1	1	1	1						D3457-1	WASHER
33	1	1	1	1						MS21043-4	NUT
34	1	1	1	1						AN4C5A	BOLT
35	1	1	1	1						NAS1149C0463R	WASHER (OR AN960C416)
36	1	1	1	1						D3413-1	RING (REPLACES D2655)
37	10	10	10	10						D2712	SET SCREW
38	2	2	2	2						D2934	SADDLE SPACER
39	2	2	2	2						D2935	SADDLE SPACER
40									2	D3414-041	GHW LUG (REPLACES D2659)
41									4	AN3C37A	BOLT
42									8	D2652	BUSHING
43									4	MS21043-3	NUT
44									4	NAS1149C0363R	WASHER (OR AN960C10)

* COPYRIGHT © 2000 BY DART AEROSPACE USA, INC *

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision: 0

Date: 11.06.15